

Automation News

PRODUCTS FOR ADVANCED TECHNOLOGY

Components

T-708
Oct. 9, 2001









Announcement of discontinued production

We would like to inform you of the discontinued products as below.












1. Already discontinued products
2. Discontinued products in 2002

1. Already discontinued products

• Relays







Products name	Old part no.	Substituted products name	Substituted part no.	Reason and remarks	Phase-out schedule
 HB relays	HB0E-00V00	DS relays  TX relays 	DS0E-00-00V0 TX2-00V	Less needs caused by decreasing demand	June. 2001
 HX relays surface-mount terminal type	HX2SA-00V-0	 TX relays surface-mount terminal type	TX2SA-00V-0	Less needs caused by decreasing demand	Aug. 2001
 HC stepping relays	HCS0-00V	None	—	Less needs caused by decreasing demand	Nov. 2001
 HZ relays	HZ1a-00V-W	 EP relays 60A type	AEP16000	Less needs caused by decreasing demand	Aug. 2001

• Relays










<p>JT relays open type</p> 	JT0-00V	None	—	Less needs caused by decreasing demand	Aug. 2001	
<p>HP relays solder terminal socket for rectangular hold boring</p> 	HPO-SRS	HP relays solder terminal socket for rectangular hold boring (with UL/CSA)		HPO-SRS*	Unified to UL/CSA approved type	Aug. 2001
<p>HP relays screw terminal socket</p> 	HPO-SF	HP relays screw terminal socket for DIN rail assembly (with UL/CSA)		HPO-SFD*	Unified to DIN rail screw terminal socket with UL/CSA	Aug. 2001
<p>HP relays screw terminal socket for DIN rail assembly</p> 	HPO-SFD	HP relays screw terminal socket for DIN rail assembly (with UL/CSA)		HPO-SFD*	Unified to UL/CSA approved type	Aug. 2001
<p>HG relays screw terminal socket</p> 	HGO-SF	HG relays screw terminal socket for DIN rail assembly (with UL/CSA)		HGO-SFD*	Unified to DIN rail screw terminal socket with UL/CSA	Aug. 2001
<p>HG relays screw terminal socket for DIN rail assembly</p> 	HGO-SFD	HG relays screw terminal socket for DIN rail assembly (with UL/CSA)		HGO-SFD*	Unified to UL/CSA approved type	Aug. 2001

• Switches / Connectors / Sensors




*Part No. suffix "-UL" is needed when ordering

Products name	Old part no.	Substituted products name	Substituted part no.	Reason and remarks	Phase-out schedule	
<p>WS switches</p> 	AWS1000 AWS9000	None	—	Less market needs and decreasing demand	Aug. 2000	
<p>Hook switches</p> 	AV8000	None	—	Less market needs and decreasing demand	Aug. 2000	
<p>GV switches</p> 	AH4000	QV micro switches		AM5000	QV switches cover all the types of GV switches and they have superior characteristics	Aug. 2001
<p>J7 switches momentary type</p> 	AJ7129B01	J7 switches		AJ7000	The market require for momentary function. *<ON>-OFF-<ON> is rare. Please recommend customers for J7 switches ON-OFF type. *< > indicates momentary position	Aug. 2001







• Switches / Connectors / Sensors

Products name	Old part no.	Substituted products name	Substituted part no.	Reason and remarks	Phase-out schedule
New J9 switches 16A type 	AJ91500○○○ AJ91510○○○ AJ92500○○○ AJ92510○○○	J9 switches 	AJ91100○○○ AJ91110○○○ AJ92100○○○ AJ92110○○○	As new J9 switches have PC board and soldering terminal of 21 A rating which is superior to J9 switches of 16 A rating. However, the lineup of J9 switches is more than New J9 switches, and, the market require for 21 A rating is rare.	Aug. 2001
Earthquake detection switches 	AHF71 AHF72	None	—	Because production items were adjusted due to decrease in numbers being sold.	June. 2001
HB relays socket AXS10HB11, AXS10HB21 	AXS10HB11 AXS10HB21	None	—	Discontinued HB relays	Aug. 2001
DR relays socket AXS10DR11, AXS10DR12 	AXS10DR11 AXS10DR12	None	—	Discontinued DR relays	Aug. 2001
ISA-bus standards card 	AXC498801	None	—	Less market needs and decreasing demand	Aug. 2001
SO-DIMM socket 	AXA110T	None	—	Less market needs and decreasing demand	Aug. 2001
PV pressure sensors 	ADP3○○○	PF pressure sensor 	ADP1○○	Because the PF pressure sensor can basically cover the market need.	Aug. 2001




• PLC

Products name	Old part no.	Substituted products name	Substituted part no.	Reason and remarks	Phase-out schedule
FP1-BASIC 	AFP10216 AFP10416 etc	FP1 (ladder type) *No compatibility in software.	AFP12217-F AFP12417-F etc	Discontinued electronic parts	End of Aug. 2001
FP3H-BASIC CPU FP3-BASIC CPU 	AFP3251 AFP3261M	FP3 (ladder type) *No compatibility in software.	AFP3211C or AFP3220C	Discontinued electronic parts	End of Aug. 2001
FP-C BASIC Control board 	AFC3260	None	—	Discontinued electronic parts	End of Aug. 2001



• PLC

Products name	Old part no.	Substituted products name	Substituted part no.	Reason and remarks	Phase-out schedule
FP3 ID/X Control Unit FP3 FD1 Control Unit 	AFP3470 AFP34701 AFP34702	None	—	Discontinued electronic parts	End of Aug. 2001
PL programmer 	APL2114	None	—	Discontinued electronic parts	End of Aug. 2001
PL power supply unit 	APL1634 APL1635 APL2634 APL2635	None Please replace with off-the-shelf product.	—	Discontinued electronic parts	End of Aug. 2001
PCWAY Ver. 1 	AFW1000	PCWAY Ver. 2	AFW1001 AFW1003	Due to latest version being sold.	Dec. 1998
FPWIN GR Ver. 1 	AFPS10110 AFPS10112 AFPS10510 AFPS11510	FPWIN GR Ver. 2	AFPS10122 AFPS10520 AFPS11520	Due to latest version being sold.	End of Aug. 2001
NPST GR Ver. 3 	AFP266731 AFP266138 AFP266538 AFP266838	FPWIN GR Ver. 2 (Windows)	AFPS10122 AFPS10520 AFPS11520	Due to latest version being sold.	End of Aug. 2001

• IMAGE CHECKER

Products name	Old part no.	Substituted products name	Substituted part no.	Reason and remarks	Phase-out schedule
IMAGE CHECKER B410/B410P 	ANB4104 ANB4124 ANB801 ANB835 ANB850	Please replace with A Series MICRO IMAGECHECKER.	—	Discontinued electronic parts	End of Aug. 2001
IMAGE CHECKER G120P 	ANG1224 ANG801 ANB835 ANB850	Succeeding product scheduled for development.	—	Discontinued electronic parts	End of Aug. 2001
Digital color select unit 	ANB7120 ANB7122 ANB7123 ANB730 ANB7505 ANB7605 ANB76003 ANB851	Please consult us about replacement.	—	Discontinued electronic parts	End of Aug. 2001

• Panel meter / Encorder

Products name	Old part no.	Substituted products name	Substituted part no.	Reason and remarks	Phase-out schedule
Panel meter LP110/120 	ALP1102 ALP1112 ALP1204 ALP1205 ALP1214 ALP1215	SUNX Limited CA2 series CA series	Thoroughly verify installation, power and I/O specifications when attempting to replace.	Discontinued electronic parts	End of Aug. 2001
Encorder ER24/40 	AER12000 AER14000	None	Please consider replacing with off-the-shelf product.	Discontinued electronic parts	End of Aug. 2001

2. Discontinued products in 2002



• Relays

Your order-in will be processed until 3 months before phase-out schedule.

Products name	Old part no.	Substituted products name	Substituted part no.	Reason and remarks	Phase-out schedule
JL relays 	JL1a0F-TMP1-00V	LE relays 	ALE10B00	Less needs caused by decreasing demand	End of Aug. 2002
JG relays 	JG1aF-00V	JV-N relays 	JVN1a0-00V	Less needs caused by decreasing demand	End of Aug. 2002
JG-P relays 	JG1aPFJ0-00V	JV-N relays 	JVN1a0-00V	Less needs caused by decreasing demand	End of Aug. 2002
JZ relays 	JZ1aFO-00V-0	JV-N relays 	JVN1a0-00V	Less needs caused by decreasing demand	End of Aug. 2002
NT relays and attachment 	NT10-00V00 NT-SS00 NT-PS00	None	—	Less needs caused by decreasing demand	End of Aug. 2002
IC unit	IC-5V IC-12V IC-24V	None	—	Discontinued electronic parts	End of May. 2002
40A type AQP relay heat sink 	AQP-HS-40A AQP802	None	—	The manufacture of accessories has been discontinued because the AQP relay has been discontinued.	End of Aug. 2002






• Relays

Your order-in will be processed until 3 months before phase-out schedule.

Products name	Old part no.	Substituted products name	Substituted part no.	Reason and remarks	Phase-out schedule
 <p>HC relay socket mounting plate</p>	HC-MOUNTING-TRACK AP3804	None	—	Less needs caused by decreasing demand	End of Aug. 2002
<p>NC relay socket mounting plate</p>	NC-MOUNTING-TRACK AW4901 AW4902	None	—	Less needs caused by decreasing demand	End of Aug. 2002
 <p>Joining plate for HP relay terminal socket</p>	HP-MOUNTING-TRACK AW5804	None	—	Less needs caused by decreasing demand	End of Aug. 2002




• Switches / Sensors / Connectors

Your order-in will be processed until 3 months before phase-out schedule.

Products name	Old part no.	Substituted products name	Substituted part no.	Reason and remarks	Phase-out schedule
 <p>NV switches standard type</p>	AH7000261 AH7000161	None	—	Because production items were adjusted due to decrease in numbers being sold.	Aug. 2002
 <p>VE rotation speed sensors</p>	ADV1000	None	—	Less needs caused by decreasing demand	Aug. 2002
 <p>QFP Sockets</p>	AXSR4000 AXS4000 AXS9000	None	—	Less needs caused by decreasing demand	Aug. 2002
 <p>SCSI standard connectors</p>	AXB3000 AXB9000	None	—	Less needs caused by decreasing demand	Aug. 2002
 <p>Connector for line card</p>	AXB5000	None	—	Less needs caused by decreasing demand	Aug. 2002



• Time relays

Your order-in will be processed until 3 months before phase-out schedule.

Products name	Old part no.	Substituted products name	Substituted part no.	Reason and remarks	Phase-out schedule
CN-K Time relays (Amber) 	AD5000	None	—	Less needs caused by decreasing demand	May. 2002
CDV Time relays 	AD4000	S1DX timer *Be careful of differences in external dimensions and contact capacity.	ADX11000	Less needs caused by decreasing demand	May. 2002
CDP Time relays 	AD7000	S1DX timer *Be careful of differences in external dimensions and contact capacity.	ADX11000	Less needs caused by decreasing demand	May. 2002

• PLC

Your order-in will be processed until 3 months before phase-out schedule.

Products name	Old part no.	Substituted products name	Substituted part no.	Reason and remarks	Phase-out schedule
PCWAY Ver. 2 set IBM printer cable type	AFW1002	None	—	Discontinued electronic parts	End of Aug. 2002
PCWAY Ver. 2 set Direct printer port type For NEC9821 Series	AFW1004	None	—	Discontinued electronic parts	End of Aug. 2002
PCWAY key unit IBM printer cable type 	AFW1032	None	—	Discontinued electronic parts	End of Aug. 2002
PCWAY key unit Direct printer port type For NEC9821 Series 	AFW1034	None	—	Discontinued electronic parts	End of Aug. 2002