

Update information (Jul.7.2014 update)

Software ver.1.02.0009/2.02.0009 → 1.02.0015/2.02.0015

● Version information

Item	Contents	Version
Setup	Installer for 32bit version	1.02.0015
	Installer for 64bit version	2.02.0015
PANATERM	PANATERM main body	5.0.3.13
ParameterConverter	Parameter file conversion software	1.0.0.9
SimMotor	Software for simulation	2.0.0.10
Setup (USBDriver)	Installer 32 bit version for USB communication device driver	1.00.0000
	Installer 64 bit version for USB communication device driver	2.00.0000
USBDriver	Device driver for 32 bit version USB communication	1.0.0.0
	Device driver for 64 bit version USB communication	1.0.0.0

● History of change point

No	Objects	Contents
1	PANATERM	We ended support for PANATERM in Windows XP. * In conjunction with that Microsoft has ended all support for Windows XP (United States time) April 8, 2014, we end support for PANATERM in Windows XP.
2	PANATERM	Added support for driver MINAS-A5ND1 series MINAS-A5N21 series, MINAS-A5L04 series and MINAS-A5LA4 series.
3	PANATERM	Updated define files for MINAS-A5B series.
4	PANATERM	Updated operation manual to the latest data.
5	PANATERM	The object data file can be opened by drag and drop to object editor screen.
6	PANATERM	Enabled to select a read source of the object, at the startup of object editor screen.
7	PANATERM	The 6 defects below were revised.

● History of correction

No	Objects	Contents
1	Object Editor	Revised on the point that sometimes the written value and the displayed value are different in EEPROM writing screen of object.
2	Object Editor	Revised on the point that the clerical error of the text at top of screen and the comment screen of object.
3	Parameter, Object Editor	Revised on the point that sometimes the exception happens when exit the screen during the receiving, reading, writing to EEPROM and file saving.
4	Additional series type setting	Revised on the point that sometimes PANATERM will not start by failure of updating the series definition file.
5	Communication with the driver	Revised on the point that it will not be able to reconnect to the driver which disconnected communication during the USB communication in some PC.
6	Version	Revised on the point that the version information of definition file of each series is not saved.