

Update information (Sep 6, 2016 update)
(Software ver.1.02.0038/2.02.0038 → 1.02.0040/2.02.0040)

● Version information

Item	Contents	Version
Setup	Installer for 32bit version	1.02.0040
	Installer for 64bit version	2.02.0040
PANATERM	PANATERM main body	6.0.0.9
ParameterConverter	Parameter file conversion software	1.0.0.9
SimMotor	Software for simulation	2.0.0.10
Setup (USBDriver)	Installer 32 bit version for USB communication device driver	1.00.0000
	Installer 64 bit version for USB communication device driver	2.00.0000
USBDriver	Device driver for 32 bit version USB communication	1.0.0.0
	Device driver for 64 bit version USB communication	1.0.0.0

● History of change point

No	Objects	Contents
1	PANATERM	Updated define files for MINAS-A5BL, MINAS-A6 and MINAS-A6N
2	PANATERM	Smoothing setting on the Frequency characteristics screen, reflected in
3	PANATERM	Added data average to trigger condition of Wave form graphic screen.
4	PANATERM	Added information of RTEX communication error on Trouble shooting
5	PANATERM	Added error information of safety diagnosis on Trouble shooting screen.
6	PANATERM	Added Deterioration diagnosis function.
7	PANATERM	The 4 defects below were revised.

● History of correction

No	Function	Phenomenone
1	Parameter	Revised on the point that the [Close] is that the menu is disabled.
2	Trouble Shooting	Revised on the point that cannot see the character at the bottom part
3	Object Editor	Revised on the point that cannot be deselect the checkbox during the
4	Block operation Editor	Added the [Help] > [Copy a screen capture to clipboard] menu.