

Update information (Nov 17, 2017 update)

Software ver.1.03.0010/2.03.0010 → 1.03.0011/2.03.0012

● Version information

Item	Contents	Version
Setup	Installer for 32bit version	1.03.0011
	Installer for 64bit version	2.03.0012
PANATERM	PANATERM main body	6.0.1.8
ParameterConverter	Parameter file conversion software	1.0.0.9
SimMotor	Software for simulation	2.0.0.10
Setup (USBDriver)	Installer 32 bit version for USB communication device driver	1.00.0000
	Installer 64 bit version for USB communication device driver	2.00.0000
USBDriver	Device driver for 32 bit version USB communication	1.0.0.0
	Device driver for 64 bit version USB communication	1.0.0.0

● History of change point

No	Objects	Contents
1	PANATERM	Changed it so that the nickname of the driver can be displayed even when it is connected with USB. (Only MINAS-A6 family released after October 2016 drivers that support wireless LAN)
2	PANATERM	Added support for drivers MINAS-A6BF series.
3	PANATERM	Updated operation manual to the latest data.
4	PANATERM	The 3 defect below were revised.

● History of correction

No	Function	Phenomenone
1	Language switching	Revised on the point that garbled when the selected language is different from the OS language.
2	Fit gain (2 degrees of freedom)	Revised on the point that sometimes the exception happens when the measurement in STEP 2 is completed.
3	Wave form graphic	Revised on the point that sometimes the error happens when exit the Wave form graphic screen.

○ Notice

About the phenomenon which Some PCs can not operate PANATERM normally after Windows update on Oct .10, fix update has been released from Microsoft®. And we are confirming the update program.

For additional information on this matter will be described below.

<https://industrial.panasonic.com/ww/products/motors-compressors/fa-motors>

[Notice for customers using setup support software "PANATERM"]