Update information
(Dec.18,2012 Software ver.1.01.0005 → 1.01.0011)

● Version information

Item	Contents	Version
Setup	Installer for 32bit version	1.01.0011
	Installer for 64bit version	2.01.0007
PANATERM	PANATERM main body	5.0.2.5
ParameterConverter	Parameter file conversion software	1.0.0.9
SimMotor	Software for simulation	2.0.0.10
USBDriver	Disk driver for USB communication	1.0.0.0

● History of change point

No	Objects	Contents	
1	PANATERM	Updated define files for MINAS-A5N and MINAS-A5NL series.	
2	PANATERM	The 4 defects below were reviseed.	

● History of correction

No	Function	Phinomenone	
1	Parameter	The following point was corrected. In Binary/Hexadecimal input screen, when 0 is inputted to bit31 from bit16, and 1 is inputted into bit15, a 32bit parameter is a negative number.	
2	Monitor	MINAS-A5L and MINAS-A5NL can monitor a CS3 input signal.	
3	Alarm	The following point was corrected. When alarm information is printed offline, alarm detailed information is not printed correctly.	
4	Communication with the driver	When [Communication with the driver] is selected and the series setting screen is canceled, "Can not detect the communication USB." does not display.	