Update information (Oct.28.2015 update)
Software ver.1.02.0023/2.02.0023 → 1.02.0029/2.02.0029

● Version information

Item	Contents	Version
Setup	Installer for 32bit version	1.02.0029
	Installer for 64bit version	2.02.0029
PANATERM	PANATERM main body	6.0.0.2
ParameterConverter	Parameter file conversion software	1.0.0.9
SimMotor	Software for simulation	2.0.0.10
Setup (USBDriver)	Installer 32 bit version for USB communication device driver	1.00.0000
	Installer 64 bit version for USB communication device driver	2.00.0000
USBDriver	Device driver for 32 bit version USB communication	1.0.0.0
	Device driver for 64 bit version USB communication	1.0.0.0

● History of change point

No	Objects	Contents	
1	PANATERM	Added support for driver MINAS-A5BL and MINAS-A6 series.	
2	PANATERM	Updated define files for MINAS-A5B series.	
3	PANATERM	Updated operation manual to the latest data.	
4	PANATERM	Added battery refresh, block operation and block operation monitor function.	
5	PANATERM	Updated layout of Wave form graphic screen.	
6	PANATERM	The 2 defects below were revised.	

● History of correction

No	Function	Phenomenone	
1	Trial run	Revised on the point that will become abnormal operation when restart the Trial run screen.	
2	Wave form graphic	Revised on the point that sometimes the exception happens when reading the file.	