Update information (Feb 25, 2016 update)
Software ver.1.02.0034/2.02.0034 → 1.02.0035/2.02.0035

● Version information

Item	Contents	Version
Setup	Installer for 32bit version	1.02.0035
	Installer for 64bit version	2.02.0035
PANATERM	PANATERM main body	6.0.0.7
ParameterConverter	Parameter file conversion software	1.0.0.9
SimMotor	Software for simulation	2.0.0.10
Setup (USBDriver)	Installer 32 bit version for USB communication device driver	1.00.0000
	Installer 64 bit version for USB communication device driver	2.00.0000
USBDriver	Device driver for 32 bit version USB communication	1.0.0.0
	Device driver for 64 bit version USB communication	1.0.0.0

● History of change point

No	Objects	Contents
1	PANATERM	The 2 defects below were revised.

● History of correction

No	Function	Phenomenone
1	Wave form graphic	Revised on the point that sometimes the error happens when start the Wave form graphic screen.
2	Wave form graphic	Revised on the point that sometimes the error happens when setting the measurement condition.