Update information (Apr 25, 2016 update)
Software ver.1.02.0035/2.02.0035 → 1.02.0038/2.02.0038

● Version information

Item	Contents	Version
Setup	Installer for 32bit version	1.02.0038
	Installer for 64bit version	2.02.0038
PANATERM	PANATERM main body	6.0.0.8
ParameterConverter	Parameter file conversion software	1.0.0.9
SimMotor	Software for simulation	2.0.0.10
Setup (USBDriver)	Installer 32 bit version for USB communication device driver	1.00.0000
	Installer 64 bit version for USB communication device driver	2.00.0000
USBDriver	Device driver for 32 bit version USB communication	1.0.0.0
	Device driver for 64 bit version USB communication	1.0.0.0

● History of change point

No	Objects	Contents
1	PANATERM	Updated define files for MINAS-A5II, MINAS-A6 and MINAS-A6N series.
2	PANATERM	The 2 defects below were revised.

● History of correction

No	Function	Phenomenone
1	Trial run	Revised on the point that will become abnormal stop during test operations.
2	Fit gain (2 degrees of freedom control)	Revised on the point that will become abnormal stop during the measurement.