

Update information (Dec 18, 2017 update)
(Software ver.1.03.0011/2.03.0012 → 1.03.0012/2.03.0013)

● Version information

Item	Contents	Version
Setup	Installer for 32bit version	1.03.0012
	Installer for 64bit version	2.03.0013
PANATERM	PANATERM main body	6.0.1.9
ParameterConverter	Parameter file conversion software	1.0.0.8
SimMotor	Software for simulation	2.0.0.10
Setup (USBDriver)	Installer 32 bit version for USB communication device driver	1.00.0000
	Installer 64 bit version for USB communication device driver	2.00.0000
USBDriver	Device driver for 32 bit version USB communication	1.0.0.0
	Device driver for 64 bit version USB communication	1.0.0.0

● History of change point

No	Objects	Contents
1	PANATERM	Some specification has been changed in connection with Windows update on Oct. 10th. Please see below for the details.

○ Notice

There was the symptom in which Some PCs didn't normally operate PANATERM after Windows update on Oct. 10th. However, applying the latest version of Windows update as of Nov. 15th can eliminate the symptom. We are sorry to trouble you, but please install the latest PANATERM (Ver.6.0.1.9), as well as the latest Windows update.

For your information, change history associated with the Windows update on Oct. 10th is described below.

- (1) There was the symptom in which PANATERM didn't load the Excel files after Windows update on Oct. 10th (before Ver.6.0.1.6).
- (2) The Excel driver was changed in PANATERM (Ver.6.0.1.7).
- (3) The read processing in the Excel files of PANATERM was changed (Ver.6.0.1.8).
- (4) The acquisition process of the numerical value and character string information was changed (Ver.6.0.1.9).