

Update information (Oct 31, 2018 update)

(Software ver.1.03.0015/2.03.0017 → 1.03.0016/2.03.0018)

● Version information

Item	Contents	Version
Setup	Installer for 32bit version	1.03.0016
	Installer for 64bit version	2.03.0018
PANATERM	PANATERM main body	6.0.1.13
ParameterConverter	Parameter file conversion software	1.0.0.9
SimMotor	Software for simulation	2.0.0.10
Setup (USBDriver)	Installer 32 bit version for USB communication device driver	1.00.0000
	Installer 64 bit version for USB communication device driver	2.00.0000
USBDriver	Device driver for 32 bit version USB communication	1.0.0.0
	Device driver for 64 bit version USB communication	1.0.0.0
Operation manual	Set up support software PANATERM Ver. 6.0	3.05

● History of change point

No	Contents
1	Installer
2	PANATERM
3	PANATERM
4	PANATERM
5	PANATERM
6	Operation manual
7	PANATERM

All version numbers of PANATERM main unit are displayed.
Updated define files for MINAS-A5MN series.
Additional support for drivers MINAS-A6 series Ver1.10.
Additional support for drivers MINAS-A6N series Ver1.23.
Additional support for drivers MINAS-A6B series Ver1.05.
Updated operation manual to the latest data.
The 5 below were fixed.

● History of correction

No	Symptoms
1	Parameter, Object Editor, Block operation Editor
2	Gain Tuning
3	Trial run
4	Status bar
5	Series type setting

When reading from a file, it changed so that EEPROM writing can not be done until it is sent to the amplifier
It was invalid in the case of the menu bar> File> Send> parameter reception menu can not be operated.
Reduced the probability of occurrence of mode error.
When the selected language is Chinese, the content displayed at the time of reconnection was changed to Japanese has been corrected.
The size can now be changed.