$\frac{\text{Update information}}{(\text{Software ver.1.03.0025/2.03.0027} \rightarrow 1.03.0026/2.03.0028)}$

Version information

| Item | Contents | Version |
|--------------------|--|-----------|
| Setup | Installer for 32bit version | 1.03.0026 |
| | Installer for 64bit version | 2.03.0028 |
| PANATERM | PANATERM main body | 6.0.1.20 |
| ParameterConverter | Parameter file conversion software | 1.0.0.9 |
| SimMotor | Software for simulation | 2.0.0.10 |
| Setup (USBDriver) | Installer 32 bit version for USB communication | 1.00.0000 |
| | device driver | |
| | Installer 64 bit version for USB communication | 2.00.0000 |
| | device driver | |
| USBDriver | Device driver for 32 bit version USB communication | 1.0.0.0 |
| | Device driver for 64 bit version USB communication | 1.0.0.0 |
| Operation manual | Set up support software PANATERM Ver. 6.0 | 3.09 |

• History of change point

| No | Objects | Contents |
|----|-----------|---|
| 1 | Operation | Updated operation manual to the latest data |
| | manual | |
| 2 | PANATERM | The 1 below were fixed. |

History of correction

| No | Function | Symptoms | |
|----|------------------|---|--|
| 1 | Wireless LAN / | Wrong description about wireless communication was corrected. | |
| | Driver | | |
| | information set- | | |
| | an | | |