<u>Update information</u> (Dec.28,2009 Software ver.1.00.0032 → 1.00.0033)

History of change point

No	Objects	Contents
1	Setup	Link to the operation manual was added to Windows menu.
2	PANATERM	Errors in writing of English and Chinese were revised.
3	PANATERM	Binary /Hexadecimal transfering function were added to a parameter screen.
4	PANATERM	It was changed to be able to carry out the axis confirmation function of the connection screen with the amplifier while It is connected.
5	PANATERM	Data save speed was improved.
6	PANATERM	Damping filter frequency automatic setting function was added.
7	PANATERM	Seven malfunction showed below was revised.
8	SimMotor	Part of the simulation calculations was revised.
9	SimMotor	Aspect of the graph indication and one part of the operation were revised.

History of correction

No	Function	Phinomenone
1	File processing	It was revised on the point that an exception error occurred when reading a file with parameters without opening a parameter screen,
2	, ,	It was revised on the point that the initial folder of the file choice was reset into the installation folder of PANATERM, in Windows Vista .
3	trial run	It was revised on the matter that the dialogue indication at the time of the error outbreak did not disappear.
4		It was revised on the matter that two times of confirmation dialog was indicated two times, when a file is overwritten and saved with the same name.
5	language reshufflir	It was revised on the matter that language switching was canceled on the way.
6		It was revised on the matter that the trigger which was not used was reset into the actual speed.
7	-	It was revised on the matter that it was sometimes not indicated even if the button was pushed .